PROCEDIMIENTO PARA ACTUALIZACIÓN DE FIRMWARE DE LA CÁMARA IDS-TCM203-A/0832

Observación: La actualización debe realizarse en 2 pasos

PASO 1

- 1- Ingresar a Device Configuration/System Maintenance/
- 2- En Configuration File elegis el archivo alg.img
- 3- Darle click al botón IMPORT

Reset all the parameters, except the IP parameters and user information, to the default settings. Restore the device to the factory default status.			
Reset all the parameters, except the IP parameters and user information, to the default settings. Restore the device to the factory default status.			
Restore the device to the factory default status.			
•			
Import All			
C:\fw\alg.img Browse Import			
Browse Upgrade			
Note : The upgrading may take 1 to 10 minutes. Please do not power off the device during upgrading.			

PASO 2

- 4- En UPGRADING FILE elegís el archivo digicap.dav
- 5- Darle click al botón UPGRADE.
- 6- Reiniciar el equipo

Export Configuration File		
Export		
Import Configuration File		
Importing Method	Import All	
Configuration File	Browse Import	
Status		
Upgrade		
Upgrading File	C:\fw\digicap.dav Browse Upgrade	
Status		
Note: The upgrading may take 1 to 10 minutes. Please do not power off the device during upgrading.		

Observación: Chequear si los firmwares coinciden con esta imagen:

Basic Information		
Device Name	IP CAPTURE CAMERA	
Device No.	88	
Model	iDS-TCM203-A	
Serial No.	iDS-TCM203-A 20210409AIF81672278	
Firmware Version	V4.2.5 201202	
Encoding Version	V4.0 build 191114	
Hardware Version	0x433900	
Number of Channels	1	
Number of Trigger Input	2	
Number of Trigger Output	2	
Smart Module Status	normal_3_ma start ok	

Algorithms Library Version

ALG	v2.2.0 build20201202
LPR	13.0.2 20-11-30
VCR	0.0.0 00-00-00
VTR	9.0.0 18-04-23
ISP	1.2.1 18-11-27
AEC	2.6.7 17-11-13
AWB	2.4.2 17-2-23
DSP	4.0.0 19-11-14
BSP	v2.0.34326
VSD	0.0.0 00-00-00
VSB	0.0.0 00-00-00
VFR	9.0.2 18-04-23
VTS	2.2.2 18-10-26