

Upgrade Procedure for Version 1.21

1. SCOPE (uSD Card Issues)

Instruct customers to perform this procedure on HD77 cameras **prior to upgrading the cameras to latest FW version.**

Each customer will have to verify the μ SD card in their cameras. If the μ SD card is identical to one of the pictures shown in Figure 1, customers should switch it from the internal slot to the external slot **prior** to performing any firmware upgrade.




Figure 1 μ SD Card pictures



Figure 2 HD77 Camera External vs Internal slot