

Turbo HD DVR v3.4.92 build170809 Release Notes (2017-09-05)

Firmware Basic Information	Firmware Version:	v3.4.92 build170809
	SDK Version:	V5.2.5.40_build20161102
	Play Library (PlayCtrl.dll)	6.2.0.3
	player	7.3.0.74
	Web version	V4.0.1 build161019
	Client version	V2.5.4.1 build20161121

Reason of Upgrade

This version is only suitable for DS-7204/08HUHI-F1/S, DS-7204/08/16HUHI-F2/S. Add some new functions, modify some functions, enhance products quality and meet customers' requirements.

Modified functions

- i. Optimized video stream strategy for remote live viewing. With hik-connect (version 3.0.0) a better response time is achieved.
- ii. More compatible with the method of adding IPC by its domain name.
- iii. Fixed the issue that controlling device by remote control failed when device number of unit was from 100 to 254.
- iv. Other bugs fixed.

Related product list:

-F/S Series Turbo HD DVR	DS-7204HUHI-F1/S、DS-7208HUHI-F1/S、 DS-7204HUHI-F2/S、DS-7208HUHI-F2/S、DS-7216HUHI-F2/S
-----------------------------	--

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com